



Photo 14. Cross section of hole #25 showing deformed material to a depth of 5 μm (0.20 mills). Mag 500X.