



Photo 17 - View of N3333S upper surface of the empennage located behind the cabin area. Note a gray paint transfer.