



Photo 17. Hole #1A. Longitudinal section showing remelt material with cracks and overheated material (above B-transus) with transformed B. The section is located at arrow A in photo 16. Mag 500X.