



Photo 21. A close up of the center of the BEA indication in hole #1B. The grey area G is contaminated with iron (Fe) in difference with the blue area B. Notice the crack in the area.