



Photo 24. Cross section of the indication area in hole #57. The microstructure shows deformation to a depth of 0.2 mm (0.0079 inch). Mag. 32X.