



Photo 25. A close up on the indication area in hole #57 in previous photo. During the drill breakdown particles on tungsten (W) have been pressed into the ID.