



Photo 4. Backscatter electron image photomicrograph of polished surface containing "hardened layer" and at least 29 cracks. The red arrows in Regions 1 and 2 identify observed plastic deformation under the "hardened layer".