

Photo 1 – Airplane as Viewed During Recovery



Photo 2 – Right Vacuum Pump as Viewed (Post Recovery)



Photo 3 - Left Vacuum Pump as Viewed (Post Recovery)



Photo 4 – Horizontal Situational Indicator (HSI) as Viewed (Post Disassembly)