



Photo 1 – Accident Site Wreckage



Photo 2 – Accident Site View of Wings and Damaged Flaperon Attach Points