



Photo 1 – photo of left outboard wing damage



Photo 2 – photo of left outboard wing damage and left aileron