



**Photo 1 – Photograph of airplane skid marks in grass leading up to airplane resting short of the runway. (Courtesy of FAA)**



**Photo 2 – View of left quartering front of airplane showing collapsed landing gear and damage. (Courtesy of FAA)**



**Photo 3 – Left side view of airplane. (Courtesy of FAA)**



**Photo 4 – Airport localizer equipment damage. (Courtesy of FAA)**