



Photo 1 – Digital Photograph Provided by Atlanta Air Salvage Personnel. View of the Airplane at the Accident Site




Photo 2 - Digital Photograph Provided by Atlanta Air Salvage Personnel. View of the Measured Oil Quantity



Photo 3 - Digital Photograph Provided by Atlanta Air Salvage Personnel. View of the Throttle Quadrant



Photo 4 – NTSB Digital Photograph. View of the Oil Pressure Transducer and Electrical Wiring Connection



Photo 5 - NTSB Digital Photograph. View of the Oil Pressure Transducer.