



Photo 1 – View of Main Wreckage



Photo 2 – View of Empennage and Tail Section



Photo 3 – View of Propeller and Engine Nacelle



Photo 4 – View of Left Side of Empennage



Photo 5 – View of Engine Nacelle and Cockpit Area



Photo 6 – View of Fuel Selector as Found