

Photo 1 – Main Wreckage (Photo Courtesy of FAA)



Photo 2 – Propeller (Photo Courtesy of FAA)



Photo 3 – Engine With Utility Cable Wrapped Around (Photo Courtesy of FAA)