



Photo 1 – Right Wing And Main Wreckage (Photo Courtesy of FAA)



Photo 2 – Engine (Photo Courtesy of FAA)



Photo 3 – No. 3 Cylinder Flange