



Photo 1 – Debris Path



Photo 2 – Main Wreckage



Photo 3 - Engine




Photo 4 – Engine Recovered



Photo 5 – Guillotine And Towrope



Photo 6 - Towrope