



Photo 1 – Airplane (Photo Courtesy of FAA)



Photo 2 – Left Wing Leading Edge Damage (Photo Courtesy of FAA)



Photo 3 – Left Wing Damage (Photo Courtesy of FAA)