



**Photo 1 – Main Wreckage (Photo Courtesy of Pilot)**



**Photo 2 – Left Wing Damage (Photo Courtesy of Pilot)**



**Photo 3 – Left Horizontal Stabilizer Damage (Photo Courtesy of Pilot)**