



Photo 1 – View of airplane in wooded area and damaged wing area



Photo 2 – View of main airplane wreckage