



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA19FA164



Photo 1 – View of Airplane Wreckage and Debris Path (Photo Courtesy of Foley Police)



Photo 2 – View of Airplane and Left Wing from Left Side



Photo 3 – View of Airplane and Left Wing from Rear



Photo 4 – View of Airplane from Right



Photo 5 – View of Airplane from Front



Photo 6 – Close View of Airplane from Left



Photo 7 – Propeller



Photo 8 – View of Left Stabilator and Empennage




Photo 9 – Passenger Cabin



Photo 10 – Cylinder No. 4 Piston Face



Photo 11 – Cylinder No. 4 Exhaust and Intake Valves



Photo 12 – Cylinder No. 4 Exhaust Valve Stem



Photo 13 – No. 4 Cylinder with Exhaust Valve Removed (Photo Courtesy of Lycoming)