



**Photo 1 – View of airplane nose down in a ditch**





**Photo 2 – View of broken nose gear**





**Photo 3 – View of runway environment where airplane departed runway 14**





**Photo 4 - View of top of airplane showing buckling on the top of the fuselage**



**Photo 5 - View of right side of fuselage showing buckling**