



Photo 1 – Main Wreckage Submerged (Photo Courtesy of FAA)



Photo 2 – Main Wreckage Recovered (Photo Courtesy of FAA)



Photo 3 – Right Wing Damage (Photo Courtesy of FAA)



Photo 4 – Empennage Damage (Photo Courtesy of FAA)