



**Photo 1 – Overview of Airplane at the Accident Site (Photo Courtesy of FAA)**



Photo 2 - View of Cockpit (Photo Courtesy of FAA)



**Photo 3 – View of Substantially Damaged Rudder (Photo Courtesy of FAA)**



**Photo 4 – Fuel Sample from the Left Wing (Black Cap) and Header Tank (Red Cap) (Photo Courtesy of the Pilot)**



**Photo 5 – View of Engine and Airframe Located at the Recovery Facility (Photo Courtesy of FAA)**



**Photo 6 – View of Engine Driven Fuel Pump (Photo Courtesy of Rotax)**