



**Photo 1 – View of wreckage during recovery. (Photo courtesy of the FAA)**



**Photo 2 – View of the seats and wing after recovery. (Photo courtesy of the FAA)**



**Photo 3 – View of the right side of the wreckage. (Photo courtesy of the FAA)**





**Photo 4 – View of the left side of the wreckage. (Photo courtesy of the FAA)**