



Photo 1 – Main Wreckage (Photo Courtesy of Airport Manager)



Photo 2 – Right Wing Damage (Photo Courtesy of Airport Manager)



Photo 3 – Tailwheel And Airframe Damage (Photo Courtesy of FAA)



Photo 4 – Empennage (Photo Courtesy of FAA)