



Photo 1 – Photo of the recovered airplane. Photo courtesy of McLarens Insurance Company.



Photo 2 - Photo of the damaged right lift strut. Photo courtesy of McLarens Insurance Company.



Photo 3 - Photo of the damaged right lift strut. Photo courtesy of McLarens Insurance Company.