



Photo 1 – Main Wreckage (Photo Courtesy of FAA)




Photo 2 – Fuel Selector Handles (Photo Courtesy of FAA)



Photo 3 – Main Wreckage Recovered (Photo Courtesy of FAA)



Photo 4 – Left Engine Top Spark Plugs (Photo Courtesy of Extreme Aviation)



Photo 5 - Right Engine Top Spark Plugs (Photo Courtesy of Extreme Aviation)