



Photo 1 – View of front of airplane with left main landing gear collapsed



Photo 2 – View of right side of airplane off of the runway in the grass



Photo 3 – View of left side of airplane showing left main collapsed gear



Photo 4 – View of left wing showing spar damage