



**Photo 1 – Front View of Main Wreckage – Courtesy of Virginia State Police**



**Photo 2 – Right Side View of Main Wreckage – Courtesy of Virginia State Police**



**Photo 3 – Close Up View of Right Side of Main Wreckage - Courtesy of Owner/Operator**



**Photo 4 – View of Empennage – Courtesy of Virginia State Police**