



Photo 1 – View of airplane in heavy brush, upper wing fuselage buckled



Photo 2 – View of airplane and right wing damage