



**Photo 1 – Main Wreckage (NTSB Photo)**





**Photo 2 - Main Wreckage (NTSB Photo)**





**Photo 3 - Main Wreckage (NTSB Photo)**





**Photo 4 - Main Wreckage (NTSB Photo)**





**Photo 5 - Main Wreckage (NTSB Photo)**





**Photo 6 – Aft Fuselage (NTSB Photo)**





**Photo 7 – Forward Fuselage (NTSB Photo)**





**Photo 8 – Emergency Exit (NTSB Photo)**





**Photo 9 – Cabin Entry Door (NTSB Photo)**





**Photo 10 – Left Main Landing Gear (NTSB Photo)**





**Photo 11 – Nose Landing Gear (NTSB Photo)**





**Photo 12 – Cockpit (NTSB Photo)**





Photo 13 – Throttle Quadrant (NTSB Photo)





**Photo 14 – Cockpit Voice Recorder (NTSB Photo)**





**Photo 15 – Point of Initial Right Wing Tip Impact on Runway (NTSB Photo)**





**Photo 16 – Departure End of Runway 24 (NTSB Photo)**





**Photo 17 – Creek Bed and Airport Perimeter Fence (NTSB Photo)**





**Photo 18 - Creek Bed and Airport Perimeter Fence (NTSB Photo)**





**Photo 19 – Aerial View of Wreckage Site (Sheriff Office Photo)**





**Photo 20 – Recovery of Fuselage (NTSB Photo)**