



**Photo 1 – View of nose of airplane on right side showing buckling of fuselage**



**Photo 2 – View of buckled firewall**



**Photo 3 – View of failed nose steering rod end**



**Photo 4 – View of failed rod end threads showing rust**