



Photo 1 – View of accident airplane at the accident site (Photo Courtesy of FAA)



Photo 2 – View of substantially damaged engine mount (Photo Courtesy of FAA)



Photo 3 – View of damaged left wing (Photo Courtesy of FAA)