



Photo 1 – View of accident airplane inverted at accident site (Photo Courtesy of FAA)



Photo 2 - View of the propeller and engine at the accident site (Photo Courtesy of FAA)



Photo 3 – Internal view of the #5 cylinder exhaust valve and metal fragments as viewed with a borescope (NTSB Photograph)