



**Photo 1 – Airplane damage, right wing.**



**Photo 2 – Airplane damage, propeller assembly.**





**Photo 3 – Airplane, left side.**



**Photo 4 – Airplane damage, right wing.**





**Photo 5 – Airplane, top of fuselage and wing.**