



Photo 1 – Damage to the right wing. Photo courtesy of the pilot.



Photo 2 - Damage to the right wing. Photo courtesy of the pilot.