



Photo 1 – Runway scrapes leading up to airplane off the side of the runway; airplane is upside down. (Courtesy of FAA)



Photo 2 – Tire skid marks in grass leading up to airplane; airplane is upside down. (Courtesy of FAA)



Photo 3 – Wrinkles and tears in bottom of right wing. (Courtesy of FAA)



Photo 4 – Damage to top of right wing. Courtesy of FAA)