





**Photo 1 – Left front view of airplane in grass. (Courtesy of Operator)**



**Photo 2 – Right front quarter view of airplane showing substantial damage to fuselage. (Courtesy of Operator)**



**Photo 3 – View of buckled firewall and a bent engine mount. (Courtesy of Operator)**