



**Photo 1 – Photo of the airplane on the morning of the accident**



**Photo 2 – Photo of the cockpit on the morning of the accident**



**Photo 3 – View of the airplane wreckage at the accident site**



**Photo 4 – View of wreckage being placed in a hangar**



**Photo 5 – View of the top of the wing**



**Photo 6 – View of the left side of the airplane**



**Photo 7 – View of the left side of the empennage**



**Photo 8 – View of the right side of the empennage**





**Photo 9 – View of the right lower wing and fuselage**



**Photo 10 – View of the left wings and fuselage**



**Photo 11 – Photo of the instrument panel**



**Photo 12 - Overhead view of front cockpit**



**Photo 13 – View of fracture surface of front control stick**



**Photo 14 – View of rear seat and control stick**




**Photo 15 – View of the top of the engine and propeller**



**Photo 16 – View of the engine driven fuel pump**





**Photo 17 – View of engine driven fuel pump**