



**Photo 1 – View of the wreckage from the front of the airplane**



**Photo 2 – View of the wreckage from the left of the airplane**



**Photo 3 – The wreckage viewed from the rear of the airplane**



**Photo 4 – View of the empennage**



**Photo 5 – View of the right side of the airplane**



**Photo 6 – View of the airplane propeller**



**Photo 7 – View of engine oil on the bottom side of the right wing**



**Photo 8 – View of the airplane’s opened door**





Photo 9 – Pilot's instrument panel



Photo 10 – View of pressurization settings



Photo 11 – View of circuit breaker panel



Photo 12 – Copilot’s Instrument Panel



**Photo 13 – Cabin Pressurization Dump Valves**



**Photo 14 – View of the top of the engine**



**Photo 15 – View of the cabin door and the pressurization seal**



**Photo 16 – View of propeller blade**





Photo 17 – View of propeller blade



**Photo 18 – View of propeller blade**