



Photo 1 – View of the aircraft in a field of tall grass



Photo 2 – View of the airplane from the left front



Photo 3 – View of the airplane from the front



Photo 4 – View of the damage to the fuselage forward of the tail