

Photographs

(Number of pages excluding this cover sheet – 1)
CD-ROM enclosed



National Transportation Safety Board

List of Photographs HWY-00-F-H001

1. Aerial view of the accident location.
(New York State Police photograph)
2. View from NY State Route 7 of the westbound approach to the intersection.
(NTSB photograph)
3. Additional view of the westbound approach to the intersection.
(NTSB photograph)
4. View showing the west and north approaches to the intersection.
(NTSB photograph)
5. Additional view showing the west and north approaches to the intersection.
(NTSB photograph)
6. View from NY State Route 30-A of the northbound approach to the intersection
(NTSB photograph)
7. Additional view from NY State Route 30-A of the northbound approach to the intersection
(NTSB photograph)
8. View of the advertisement on the north side of the intersection.
(NTSB photograph)
9. View looking west of the tire marks leading up to the area of impact.
(NTSB photograph)
10. Additional view looking west of the tire marks leading up to the area of impact.
(NTSB photograph)
11. View looking west of the pre and post impact tire marks.
(NTSB photograph)