

PEDESTRIAN SIR-HIGHWAY ACCIDENT BRIEF

Scene Photos

Falls Church, VA (2)

HWY16SH013

(5 pages)



Photo 1- A view facing southbound on Graham Road showing the *crosswalk ahead* plaque, north of the collision scene



Photo 2 – A view facing northbound on Graham Road showing the pedestrian warning signs with *diagonal arrow* plaques (circled in red) at collision scene



Photo 3 – A view facing southbound on Graham Road showing the *crosswalk ahead* plaque and the pedestrian warning signs with *diagonal arrow* plaque (circled in red) the area of impact is shown by the red arrow



Photo 4 - A closer view facing southbound, of the crosswalk with the area of impact circled in red



Photo 5 - A view of the crosswalk facing west and pedestrian warning sign



Photo 6 - A view of the crosswalk facing west showing direction of travel of the pedestrian



Photo 7 – A view of the overhead light above the crosswalk



Photo 8 - A view of the scene facing northbound, the area of impact is shown by the red arrow