



HIGHWAY ACCIDENT BRIEF PHOTOGRAPHS


Capitol Heights, Maryland

HWY16SH021

(3 pages)



Photograph 1- Southbound lanes of Central Avenue and pedestrian crosswalk – facing north



Photograph 2 – Rear of Volks Wagon Jetta at position of final rest



Photograph 3 – Front right corner of Volks Wagon Jetta showing damage to grille and hood



Photograph 4 – Front left side of Volks Wagon Jetta showing damage on left wheel and hood