



HIGHWAY ACCIDENT BRIEF

Photographs

Town of Geneva, Wisconsin

HWY16SH022

(6 photographs)



Photograph 1 – Eastbound Traffic Lanes at Crash Location – Facing East During Daylight Hours



Photograph 2 – Eastbound Traffic Lanes at Crash Scene Showing Debris Evidence – Facing East (source: Wisconsin State Patrol)



Photograph 3 – Eastbound Traffic Lanes at Crash Scene Showing Debris Evidence – Facing East (source: Wisconsin State Patrol)



Photograph 4 – Front Driver's Side Corner of Ford Expedition Showing Contact Damage



Photograph 5 - Front of Ford Expedition Showing Contact Damage



Photograph 6 – Contact Damage to Roof of Ford Expedition