



Photo 1 – Supplied image of the right-side fuselage. The fuselage exhibits wrinkle deformation.