



Photo 1 – View of a tree near the accident site. (Supplied Photo)



Photo 2 - View of the airplane at the accident site during recovery. (Supplied Photo)



Photo 3 - View of the fuel gauge and fuel tank sender selector switch. (Supplied Photo)



Photo 4 - View of the fuel tank selector valve. (Supplied Photo)



Photo 5 - View of the airplane at the accident site during recovery. (Supplied Photo)



Photo 6 - View of the airplane engine at the accident site during recovery. (Supplied Photo)



Photo 7 - View of a propeller blade during recovery. (Supplied Photo)



Photo 8 - View of a flight control cables during recovery. (Supplied Photo)



Photo 9 - View of a flight control cables during recovery. (Supplied Photo)



Photo 10 - View of the wreckage on a recovery trailer. (Supplied Photo)