



Photo 1 – Aerial view of accident site



Photo 2 – View of airport from overhead the accident site



Photo 3 – View of accident site looking back toward the airplane’s descent through the trees



Photo 4 – View of accident site from the side of the airplane



Photo 5 – View of accident site from rear of airplane



Photo 6 – View of engine and propeller at the accident site



Photo 7 – One of several tree branches which were cut by propeller



Photo 8 – View of engine and propeller at recovery location