



**Photo 1 – Firewall and engine mount damage (Courtesy of FAA)**



**Photo 2 – Right wing damage (Courtesy of FAA)**





**Photo 3 – Rudder damage (Courtesy of FAA)**



**Photo 4 – Elevator damage (Courtesy of FAA)**