



Photo 1 – Main Wreckage (NTSB Photo)



Photo 2 – Main Wreckage (NTSB Photo)



Photo 3 – Empennage (NTSB Photo)



Photo 4 – Aft Fuselage and Empennage (NTSB Photo)



Photo 5 – Empennage (NTSB Photo)



Photo 6 – Left Wing and Empennage (NTSB Photo)



Photo 7 – Forward Fuselage (NTSB Photo)




Photo 8 – Cockpit Area (NTSB Photo)




Photo 9 – Engine (NTSB Photo)



Photo 10 – Right Wing (NTSB Photo)



Photo 11 – Right Wing (NTSB Photo)



Photo 12 – Nose Landing Gear (NTSB Photo)




Photo 13 – Engine Controls (NTSB Photo)



Photo 14 – Engine Tachometer (NTSB Photo)



Photo 15 – Engine Vacuum Pump (NTSB Photo)



Photo 16 – Engine Vacuum Pump (NTSB Photo)



Photo 17 – Top Spark Plugs (NTSB Photo)



Photo 18 – Bottom Spark Plugs (NTSB Photo)



Photo 19 – Engine Propeller (NTSB Photo)



Photo 20 – Engine Propeller (NTSB Photo)